

Operation Instructions

Mini Pedometer With One Key

Features:

1. Pedometer (Step Counter) adopts microcomputer technology with mini-construction design and readable LCD display. The paces are detected via the movement of waist.
2. Step counts range from 0 to 99999.
3. Reset key to clear the records.
4. It will auto turn off after not in use for one and half minutes.

Mounting:

Attach the pedometer securely to your waistband or belt, Close to the center of your body . False mounting or walking way will possibly cause inaccurate result.

Measurement:

1. RESET key is used..
2. Start the measurement by pressing the " RESET" key.
3. Clear all the amounts memory when starting the new measurement.



Notes:

1. For this precise instrument, please make sure to operate and maintain properly.
2. Don't disassemble the instrument except replacing battery, or will cause damage to it or influence on its measuring accuracy.